Report of Inspection/Test Joint Commission 2019

10/30/2019 Property

> Your business 123 Main Street Portland, OR 97218 Jane Smith

Print Date: 10/30/2019

Conducted by: Chris Warren, DAIT NICET Level 1 - ITM

Oregon Door Consultants 28831 SW Costa Cir W Wilsonville, OR 97070

admin@OregonDoorConsultants.com



Fire Doors - 1st flr

Inspection Summary

Identification Number	Location	Status			
1-1	1st floor hallway	Fail			
1-2	1st floor hallway	Pass			
1-3	1st floor hallway	Pass			
1-4	1st floor hallway	Pass			
1-5	1st floor hallway	Pass			
1-6	1st floor hallway	Pass			
1-7	1st floor hallway	Pass			
1-8	1st floor hallway	Pass			
1-9	1st floor exit	Pass			
1-10	1st floor exit	Pass			
1-11	1st floor exit	Pass			

Report of Inspection/Test Joint Commission 2019

10/30/2019 Property

> Your business 123 Main Street Portland, OR 97218 Jane Smith

Print Date: 10/30/2019

Conducted by: Chris Warren, DAIT NICET Level 1 - ITM

Oregon Door Consultants 28831 SW Costa Cir W Wilsonville, OR 97070

admin@OregonDoorConsultants.com



1-1					
Details					
Identification Number	1-1		Location	1st floo hallwa	
Manufacturer	Lexing	jton	Rating of Barrier	60 min	1
Has Hold Open Device	No			3	
QUESTIONS					
Is door closer rated, installed properly and functioning correctly?	O	Yes No	Is door and glazing free from excessive signage?		Yes No
		NA			NA
Is clearance from bottom of door to bottom of floor less than 3/4"?	☑	Yes	Is fire exit hardware labeled and have all latching points	☑	Yes
trian 3/4 ?		No	installed?		No
144001444464 4190		NA Yes			NA Yes
Is hinge clearance correct (1/8" +/- 1/16 for metal)?		No	Is door free from unused fastener holes?		No
	_	NA			NA
Are hinges steel, ballbearing and properly attached?		Yes	Is door properly labeled?	<u> </u>	Yes
The finiges steet, banbearing and properly attached:		No	is door properly laboled:		No
		NA			NA
Has signage been attached properly, free from nails, Yes Is door f		Is door free from delamination, damage, or rust through	\square	Yes	
screws and tacks?		No	areas?		No
		NA			NA
Is top clearance correct (1/8" +/- 1/16 for metal)?	✓	Yes	Is door lock rated, installed properly and functioning		Yes
		No	correctly?		No
		NA			NA
Does door swing freely?		Yes	Does door securely latch?		Yes
		No NA			No NA
le frame from helps brooks and gust through groop?	<u>_</u>	Yes	In frame preparity consumed?		Yes
Is frame free from holes, breaks and rust through areas?		No	Is frame properly secured?		No
		NA			NA
Is glazing, vision light frames and glazing bead properly		Yes	Does door close completely?	☑	Yes
rated, intact and securely fastened?		No	2000 0001 00000 000mp.0001).		No
		NA			NA
Is frame properly labeled?	☑	Yes	Door is free from mechanical hold open devices, including	☑	Yes
20 70 30		No	wedges and door stops?		No
		NA			NA

Report of Inspection/Test

Joint Commission 2019

10/30/2019 Property

> Your business 123 Main Street Portland, OR 97218 Jane Smith

Print Date: 10/30/2019

Conducted by: Chris Warren, DAIT NICET Level 1 - ITM

Oregon Door Consultants 28831 SW Costa Cir W Wilsonville, OR 97070

admin@OregonDoorConsultants.com



Questions with Photos and Notes

ID Number: 1-1

Location: 1st floor hallway

Does door securely latch?

No



Deficiencies - 1-1

Does door securely latch?

Notes:

We found this door's latching hardware is damaged and doesn't secure the door when it is in the closed psotion all the time. Reccomendation is to replace the latch bolt as it doesn't project far enough out.

NFPA Code Reference 5.2.3.5.2 (9) Latching hardware operates and secures the door when it is in the closed position. NFPA Code Reference 6.4.4.6.1 The throw of a single-point latch bolts shall not be less than the minimum shown on the fire door label.

Report of Inspection/Test

Joint Commission 2019

10/30/2019 Property

> Your business 123 Main Street Portland, OR 97218 Jane Smith

Print Date: 10/30/2019

Conducted by: Chris Warren, DAIT NICET Level 1 - ITM

Oregon Door Consultants 28831 SW Costa Cir W Wilsonville, OR 97070

admin@OregonDoorConsultants.com



Inspector Signature

I state that the information on this form is correct at the time and place of my inspection, and all equipment tested at this time was left in operational condition upon completion of this inspection except as noted.

Inspector Name	Signature	Date Completed
Chris Warren, DAIT		2019-10-30
	Λ_{α}	